COMPLETION REPORT

	Name Of Work	**Removals Of Silt & Debris in Ward No 13, Shettyhalli Sub Division**
2	Sanctioned Estimate No.& Date	EE/DD/AA/37/2016-17, Date:30.12.2017 EE/DD/TS/54/2016-17, Date:30.12.2017
3	Head Of Account which is chargeable	P-1771
4	Instrument Order No. & Date	EE/PD/DZ/WO/143/16-17, Date:24.03.2017
5	Name Of Contractor	**Sri. Umesh N, No.30, Ammaji Enclave, 8th Main Road, 10th Cross, Maheshwari nagara, T Dasarahalli, Banglore.**
5 a	Time Stipulated for Completion of work	**180 Days**
6	Delay in Exculpation of Work	**No Delay**
7	Measurement recorded in	M.B No: 4891/16-17 Page No: 489030 - 32
8	Check Measurement of the Asst Exe. Eng./ Exe, Eng., On	M.B No, - do - Page No, - do -
9	Name of the office/official in charge of the work	
10	a) Asst.Eng/Junior Eng	Sri. Suresh Devathraj AE
	b) Asst.Exe Engineer	Sri.B.L.Jayalingappa

Sanctioned Estimate Amount	Amount Claims As Per Actually Vide As per bills	DIFFERANCE	
		Excess	Savings
Rs. 10.00 Lakhs	968,346.00		

1) Certified that the above work has been completed within the stipulated time noted in the
2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
3) Certified that the above work has been executed by the contractor satisfactory in

ASSISTANT ENGINEER

EXECUTIVE ENGINEER - 2,
Bruhat Bangalore Mahanagara Palike,
Dasarahalli Division, Bangalore-57.

ASSISTANT EXECUTIVE ENGINEER
ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾ.ಎಂ. ರಸ್ತೆ, ದಾಸರಹಳ್ಳಿ, ಬೆಂಗಳೂರು

Scanned by CamScanner